# Oil Field Environmental Incident Summary

**Responsible Party:** CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: BAILEY 6-24H1

Field Name: PERSHING Well File #: 28563

Date Incident:1/13/2015Time Incident:11:20Facility ID Number:County:MCKENZIETwp:150Rng:97Sec:25Qtr:

Location Description: Lease Road

Submitted By: Todd Senescall Received By:

Contact Person: Brian Koskovich

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Other - Described Above Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 2 Barrels 2 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 11/22/2016 Clean Up Concluded: 1/13/2015

Risk Evaluation:

none

Areal Extent:

Approximately 700 linear feet, contained on the lease road.

## Potential Environmental Impacts:

soil

## Action Taken or Planned:

Source of the release is under investigation. Contaminated scoria on the road will be recovered for disposal.

Wastes Disposal Location: TBD

Agencies Involved: NDIC Inspector Joyce Kohut

# **Updates**

Date: 1/16/2015 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

Release, due to a leak from a transport truck, remained on the location lease road according to the report. NDIC retains oversight.